



**AEROSEAL.**



## Case Study

MEZ-AEROSEAL

# Seven street restoration

» Sealing after 2 years of building operation and reduction of a total leakage by approx. 93.3% «

## Seven street restoration

**Location:** 1 SIEDMIOGRODZKA STREET, WARSAW, Poland

**Date:** -

**MEZ-AEROSEAL Partner:** Energy Air Sp. z o.o

**Executing company:** -

**Result:** -



Smell



Noise



Energy efficiency



Air tightness



Indoor air quality

### Description

The restaurant is located in an apartment building in Warsaw's Wola district. Sealing with AEROSEAL® technology included an exhaust shaft from the kitchen hood. The main problem, which was successfully solved, was the penetration of annoying smells from the exhaust shaft into private apartments located on 7 floors above the restaurant.

## Successful sealing

With our successful MEZ-AEROSEAL partner network we achieve great success again and again.

## The change in leakages

### Before sealing

- 348,5 m<sup>3</sup>/h

### After sealing

- 23,4 m<sup>3</sup>/h

### Reduction

- 93,30%



[www.mez-technik.com](http://www.mez-technik.com)



[info@mez-technik.de](mailto:info@mez-technik.de)



+49 (7072) 600980